



DISPLAY UNIT

“How To” – Finish a Job & Send Back to TMOL

1. From your main screen Press “MENU”
2. Select “Finish Job”
3. Press “ENT”
4. Press “OK”
5. Job will now be sent back to TMOL via Wireless

TRACMAP

www.tracmap.com